

ORIGINAL



0000080606

Mount Tipton Water Company

RECEIVED

50

Docket No. W-02105A-04-0880

2008 JAN 17 P 12:40

Docket NO. W-02105A-03-0303 and 67162

AZ CORP COMMISSION
DOCKET CONTROL

ADEQ Drinking Water Compliance Status Report

Arizona Corporation Commission

DOCKETED

JAN 17 2008

DOCKETED BY

Arizona Department of Environmental Quality
Drinking Water Monitoring and Protection Unit
1110 W. Washington Street, 5415B-1
Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name: Mt. Tipton Water Co.

Public Water System ID #: 08-059

Public Water System Type: ☒ Community ☐ Non-transient Non-community ☐ Transient Non-community

Overall Compliance Status: ☐ No Major Deficiencies ☒ Major Deficiencies

Monitoring and Reporting Status: ☐ No Major Deficiencies ☒ Major Deficiencies

Comments:

This system has exceeded the MCL for total coliform in April 2007. The ADEQ data base does not show that this water system has provided the calendar year 2005 and 2006, consumer confidence report; that the required 2005 and 2006 annual nitrate analyses have been done at EPDS004; that the required 2nd, 3rd and 4th quarter nitrate analyses have been done after exceeding a trigger for increased nitrate monitoring at EPDS010 on 3-29-06; or that the required 2nd quarter nitrate analyses have been done after exceeding a trigger for increased nitrate monitoring on 2-3-04 and the 3rd, 4th quarter after exceeding a nitrate trigger on 2-15-2006, at EPDS002.

Operation and Maintenance Status: ☒ No Major Deficiencies ☐ Major Deficiencies

Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- | | |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi | <input type="checkbox"/> inadequate storage |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies | <input type="checkbox"/> approval of construction |
| <input type="checkbox"/> certified operator | <input type="checkbox"/> other |

Date of last inspection / sanitary survey: 3-15-2007

Administrative Orders:

Is an ADEQ administrative order in effect? ☐ Yes ☒ No

Comments:

System information:

Number of Entry Points to the Distribution System 6 Number of Sources 8
Population Served 2000 Service Connections 890 Initial Monitoring Year 1994

Evaluation completed by: Jim Puckett, Environmental Health Specialist II

Phone: 602-771-4649 **Date:** 8-30-07

Because of the previously identified exceedance and compliance monitoring deficiencies, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.